



## WARNING

Due to the obsolescence of the Bluetooth chip, products starting from serial n. 0012223 will not be equipped with bluetooth function.

We inform you that all the parameters related to Bluetooth, mentioned in the Quick Guide and Owner's manual, are no longer active.